FRONT PAGE

BUYERS GUIDE

IMPORTANT: Spoken promises are difficult to enforce. Ask the dealer to put all promises in writing. Keep this form.

Chevrolet

TrailBlazer

2006

1GNDT13S562344214

VEHICLE MAKE

MODEL

YEAR

VEHICLE IDENTIFICATION NUMBER (VIN)

WADDANTIES FOR THIS VEHICLE:

WARRANTIEST OR THIS VEHICLE.			
X	AS IS - NO DEALER WARRANTY THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE.		
	DEALER WARRANTY		
	FULL WARRANTY.		
	LIMITED WARRANTY. The dealer will pay% of the labor and% of the parts for the covered systems that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions, and the dealer's repair obligations. <i>Implied warranties</i> under your state's laws may give you additional rights.		
SYSTEMS COVERED: DURATION:			
NON-	DEALER WARRANTIES FOR THIS VEHICLE:		
☐ MA	NUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired on some mponents of the vehicle.		
	ANUFACTURER'S USED VEHICLE WARRANTY APPLIES.		
ОТ	HER USED VEHICLE WARRANTY APPLIES.		
Ask the	e dealer for a copy of the warranty document and an explanation of warranty coverage, exclusions, and repair iions.		
CO	ERVICE CONTRACT. A service contract on this vehicle is available for an extra charge. Ask for details about verage, deductible, price, and exclusions. If you buy a service contract within 90 days of your purchase of this hicle, <i>implied warranties</i> under your state's laws may give you additional rights.		
ACK THE DEALER IS VOLID MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.			

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safercar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of the resources on these sites.

SEE OTHER SIDE for important additional information, including a list of major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español.

Year: 2006 Make: Chevrolet Model: TrailBlazer VIN: 1GNDT13S562344214

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks-bent or twisted frame

Engine

Oil leakage, excluding normal seepage Cracked block or head

Belts missing or inoperable

Knocks or misses related to camshaft

lifters and push rods

Abnormal exhaust discharge

Transmission & Drive Shaft

Improper fluid level or leakage, excluding normal seepage

Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty

transmission or drive shaft Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

Improper fluid level or leakeage, excluding normal seepage

Cracked of damaged housing which is visible

Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage

Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

Gauges or warning devices

Air conditioner

Heater & Defroster

Brake System

Failure warning light broken

Pedal not firm under pressure (DOT spec.)
Not enough pedal reserve (DOT spec.)
Does not stop vehicle in straight line

(DOT spec.)

Hoses damaged

Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged

Air Bags

Steering System

Too much free play at steering wheel (DOT specs.)

Free play in linkage more than 1/4 inch

Steering gear binds or jams
Front wheels aligned improperly

(DOT specs.)
Power unit belts cracked or slipping

Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected

Spring broken

Shock absorber mounting loose Rubber bushings damaged or missing

Radius rod damaged or missing

Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

Wheels
Visible cracks, damage or repairs
Mounting bolts loose or missing

Exhaust System

Leakage

Catalytic Converter

NOTICE

	THE VEHICLE OF THE THE VEHICLE OF TH	ME HAS DONDED TITLE
Customer's Initials	. I/ WE HEREBY UNDERSTAND THAT THIS VEHIC	LE HAS BONDED THEE

DEALER NAME

Rick Austin Automotive, Inc.

ADDRESS

22002 State Hwy. 249 Houston ,TX 77070

TELEPHONE

EMAIL

(281) 376-6071

raassbs@yahoo.com

FOR COMPLAINTS AFTER SALE, CONTACT:

Rick Austin Automotive, Inc. -

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).